

JOB DESCRIPTION

JOB TITLE: Press Brake Operator – Production Worker

CLASSIFICATION: Non-exempt

DEPARTMENT: Fabrication

REPORTS TO: Press Brake Lead

SCHEDULE: Day Shift: Mon – Fri, 6:00 am – 2:30 pm

Evening Shift: Mon – Fri, 2:30 pm – 11:00 pm

POSITION SUMMARY: This position is responsible for the daily setup and operation of hydraulic CNC controlled press brakes in a just-in-time fabrication shop with some assistance provided. He/she may be required to assist other operators as a helper on key work or machines as required. This is a cross functional position within the Fabrication department.

RESPONSIBILITIES:

- 1. Set up and operate a hydraulic press or punch for routine established work.
- 2. Select correct tooling for the job task with setup documents or supervisor/lead assistance.
- 3. Load, install and correctly set up the tools required with some assistance from supervisor/lead.
- 4. Perform assigned work to time standards and quality expectations.
- 5. Account for time and work completed via online computer data collection system.
- 6. Safely operate a forklift to handle materials and completed work.
- 7. Make routine decisions and use problem solving to resolve basic manufacturing issues or seek assistance.
- 8. Report and document basic material, production and quality control issues.
- 9. Maintain performance log books on assigned area equipment, report deficiencies to the maintenance team.
- 10. Participate in equipment preventative maintenance at the operator level.

QUALIFICATIONS:

- 1. Must have strong metal press forming and basic fabrication background.
- 2. Minimum 1 year experience in a manufacturing environment is strongly desired.
- 3. Basic knowledge and understanding of fabrication, hydraulic press and/or punch operations including basic set up is desired.
- 4. Competent at basic dimensional measuring and able to quickly learn the use of precision measurement tools.
- 5. Demonstrated competency in basic shop math.
- 6. Basic ability to read and understand blueprints and other shop drawing aids.
- 7. Ability to work with various types of metal forming constraints with guidance.
- 8. Previous experience with overhead crane use is desired.
- 9. Ability to operate a forklift.

- 10. Flexible and responsive with a strong teamwork orientation.
- 11. Good verbal and written communication skills.
- 12. Desire to learn new skills and improve technical knowledge.
- 13. Strong orientation toward quality, safety and continuous improvement.
- 14. Ability to work well in a fast paced environment to meet team expectations.
- 15. Commitment to quality and accuracy of work performed.
- 16. Demonstrated ability to effectively implement or respond to change.
- 17. Understanding and support of Company policies and procedures.
- 18. Safety conscious behavior.
- 19. Excellent attendance.

PHYSICAL REQUIREMENTS:

- 1. Lift, carry, push and or pull 1 50 lbs frequently.
- 2. Squat/kneel, bend/stoop, twist/turn, grasp and reach overhead and outward frequently.
- 3. Sit, stand and walk for 1 10 hours per day.
- 4. Ability to work in a 55 85 degree Fahrenheit work environment.
- 5. Work in a fast paced industrial environment wearing hearing protection, vision protection, hard hat, steel-toed shoes and other appropriate protective clothing.

CLICK HERE TO APPLY

QP 6.0 - 2 - Last revised 3/15/11